

1 2 3 4 5 6

Spring feed right (standard)

Measuring Transducer T with device for fine adjustment

Spring holder T800/29000

O-ring-NBR

Measuring force (standard) spring 1.0N

Conversion to pneumatic feed right

Feed by spring

Pneumatic feed right

Pneumatics switched off advance stroke by spring

Pneumatics switched on advance stroke to the right by compressed air

Pneumatic cylinder T800/88000

O-ring-NBR

Spring holder T800/29000

O-ring-NBR

Measuring force spring 1.0N

Conversion to pneumatic feed right
(For the left-hand pneumatic feed version, the assembly is reversed)



www.peterhirt.com

1002214


Assembly drawing

Pneumatic cylinder T800/88000

Masstab / Scale

1:1.5

mm



1 2 3 4 5 6

A

B

C

D

A

B

C

D